

Product Update

SER 15-005

SpiderLine THLL New vs. Legacy Component Mixing May 21, 2015

PURPOSE

There has been some confusion if it is acceptable to mix New SpiderLine THLL with Legacy Spider-Line THLL or other Manufacture Components and whether the resultant system would meet OSHA requirements.

COMPLIANCE CATEGORY	PRIORITY CODE
Safety	\square 1
Failure to comply with this product update could result in personal	Prior to unit startup or prior to continued operation (Immediate
injury. Compliance is mandated within a specific operating time.	Action Required)
	, rouse required,
Compliance Required	□ 2
Identifies the need for action to correct a condition that, if left	At first opportunity (Prior to Next Scheduled Maintenance Interval)
uncorrected, may result in reduced equipment reliability or	
efficiency. Compliance may be required within a specific operating	
time.	
Optional	☐ 3
Identifies changes that may be beneficial to some, but not	Next Scheduled Maintenance Interval
necessarily all. Accomplishment at customers discretion.	
, '	
Notification	₩ 4
Customer communication, no action required.	Optional / Notification
castomer communication, no action required.	Optional / Notification
PRODUCT MODELS AFFECTED	
SC1000/1500 SC30 SC40 Zmac	
ST-26 ST-180 Platforms BAP	
Hoist Accessories Platform Accessories	Rigging Accessories Safety Accessories
COMPONENT SYSTEM	
☐ Electrical ☐ Mechanical	Safety Other:
SUB COMPONENT	
New SpiderLine Temporary Horizontal LifeLine system; Legacy Spider-Line (P/N P-XXXXX) components; other	
manufacture (Safe Approach) components.	
manadata (odio rippiodoli) odilipoliolilo.	

ACTION REQUIRED


The **New** SpiderLine Temporary Horizontal LifeLine system (P/N 700783-XXX) meets the requirements of ANSI Z359-2007, CSA Z259.13-04, and OSHA, when the system is comprised exclusively of New SpiderLine components (708780-1 Post with related mountings; 709026-2 Energy Absorber & 708784 Cable) and is installed per instructions in Operators Manual 709025 and labels 709018-x and 709019-x. If a combination of **New** and **Legacy** SpiderLine (P/N P-XXXXX) components is used, the system meets OSHA requirements. If **New** or **Legacy** SpiderLine components are used in combination with components from **other manufacturers**, a Competent Person must determine if the system meets OSHA requirements.






SER 15-005
SpiderLine THLL New vs. Legacy Component Mixing

piderLine THLL New vs. Legacy Component Mixing
May 21, 2015



STANCHION ASSY;THLL 708781-1 708870-1 STANCHION ASSY; DEEP; THLL 709465-1 ANCHOR ASSY;THLL;BOLT DOWN 709465-2 ANCHOR ASSY;THLL;WELD DOWN 709465-3 ANCHOR ASSY;THLL;WELD;NO PLATE STANCHION ASSY:PRE-CAST:END 710475-1 STANCHION ASSY; PRE-CAST; BASE 710476-1 708780-1 TUBE ASSY:THLL 709166-1 BRACKET ASSY;THLL;DEEP 709165-1 BRACKET ASSY;THLL 708783-60 LIFELINE ASSY;THLL;60' 708783-120 LIFELINE ASSY;THLL;120' 708783-180 LIFELINE ASSY:THLL:180' 708783-240 LIFELINE ASSY:THLL:240' 708783-300 LIFELINE ASSY;THLL;300' 708784-60 CABLE ASSY;THLL;60' 708784-120 CABLE ASSY;THLL;120 708784-180 CABLE ASSY;THLL;180' 708784-240 CABLE ASSY;THLL;240' 708784-300 CABLE ASSY:THLL:300' SHOCK ABSORBER ASSY:THU 709026-1 TURNBUCKLE ASSY;5/8X6";CLV&CTR 709164-1 595755 TURNBUCKLE;5/8 X 12 JAW-JAW A-00672-5 THIMBLE; WIRE ROPE; GALV; 5/16DEA P-00228 CARABINER;TWISTLOCK;115.7mm LG 233740 FIST GRIP;5/16"

Legacy Spider-Line: THLL Red round stanchions



Other Manufacture (Safe Approach): Orange round stanchions and Energy Absorber



Note: Legacy Spider-Line THLL and Safe Approach use similar part numbers

P-00039-1	Inline Energy Absorber
P-00149-1	2-1/4" Flange Adapter
P-00149-2	3-1/2° Flange Adapter
P-00149-3	Bolt-on Stanchion Pass Through Device
P-00149-4	Stanchion Adapter Plate
P-00041-1	Steel I-Beam Stanchion
P-00041-10	Concrete Stanchion (or Steel bolt-on)
P-00041-CA	Stanchion Chain Assembly
P-00041-1B	Stanchion Mounting Bolt
P-00041-1P	Stanchion Pin
P-00147-40	CABLE;ASSY;SPIDER-LINE;40FT
P-00147-60	CABLE;ASSY;SPIDER-LINE;60FT
P-00147-SH	Cable Assembly Shackle
P-00147-LT	Cable Assembly Adj Clamp/Thimble
P-00147-TH	Cable Assembly Thimble
P-00147-TB	Cable Assembly Turnbuckle

ACCOMPANYING DOCUMENTS

None

BOLTS