Product Update



SER 19-002

UpPro Wire Rope Lubrication Clarification February 1, 2019

PURPOSE	
A mistake was found in versions of the Dual Lift Operator's manual regarding lubrication of wire ropes. Clarification is needed.	
COMPLIANCE CATEGORY Safety Failure to comply with this product update could result in personal injury. Compliance is mandated within a specific operating time. Compliance Required Identifies the need for action to correct a condition that, if left uncorrected, may result in reduced equipment reliability or efficiency. Compliance may be required within a specific	PRIORITY CODE 1 Prior to unit startup or prior to continued operation (Immediate Action Required) 2 At first opportunity (Prior to Next Scheduled Maintenance Interval)
operating time. Optional Identifies changes that may be beneficial to some, but not necessarily all. Accomplishment at customers discretion. Notification Customer communication, no action required.	☐ 3 Next Scheduled Maintenance Interval ☑ 4 Optional / Notification
UPPRO PRODUCT MODELS AFFECTED	
Man Riding Hoists (SP or P) Material Hoists (SM or M) OSL ISL	
Hoist Accessories Rigging Accessories	Test Equipment Other:
COMPONENT SYSTEM	
Electrical Mechanical	Safety Other: Rigging
	Juicty Utility Nigging
SUB COMPONENT	
Wire Rope	
ACTION REQUIRED	
The operator's manuals prior to January 2019 mistakenly stated comments that were not meant to be in the manual regarding	
wire rope lubrication in Section 11.5.	
The two comments stated: "Regular lubrication of the wire rope ensures that the wire rope drive remains sufficiently lubricated." & "Lubrication substantially increases the service life of the wire rope drive. Proper lubrication does not adversely affect the drive capability." In addition, section 11.5.1a stated: "Always keep the wire rope slightly lubricated."	
As the wire rope is already properly lubricated from the manufacturer, additional wire rope lubrication is not required or recommended. Subsequently, the statement has been removed from the manual effective January 2019 as it was previously placed in the manual in error. Note: Always ensure proper wire rope inspection criteria are followed as outlined in the manual. Replace as necessary.	
ivote. Always ensure proper wire rope inspection criteria are rollowed as outlined in the manual. Replace as necessary.	
	<u> </u>
ACCOMPANYING DOCUMENTS	

365 Upland Drive Seattle, WA 98188 Americas 855.457.8513 ProductSupport@SpiderStaging.com www.SpiderStaging.com